

QA-54

William Huck Farm (Site)

Church Hill vicinity

Private

circa 1825-50

The early house on the William Huck Farm was a 1 1/2 story, 3 bay frame house with a gambrel roof. The interior was evidently divided into a hall-parlor plan. Probably dating to the second quarter of the 19th century, it was demolished in the late 1960's or early 1970's.

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME

HISTORIC

AND/OR COMMON

William Huck Farm

2 LOCATION

STREET & NUMBER

North side Southeast Creek Road

CITY, TOWN

Church Hill

☒ VICINITY OF

CONGRESSIONAL DISTRICT

1st

STATE

Maryland

COUNTY

Queen Anne's

3 CLASSIFICATION

CATEGORY

☐ DISTRICT☐ BUILDING(S)☐ STRUCTURE☒ SITE☐ OBJECT

OWNERSHIP

☐ PUBLIC☒ PRIVATE☐ BOTH

PUBLIC ACQUISITION

☐ IN PROCESS☐ BEING CONSIDERED

STATUS

☐ OCCUPIED☒ UNOCCUPIED☐ WORK IN PROGRESS

ACCESSIBLE

☐ YES: RESTRICTED☐ YES: UNRESTRICTED☒ NO

PRESENT USE

☒ AGRICULTURE☐ COMMERCIAL☐ EDUCATIONAL☐ ENTERTAINMENT☐ GOVERNMENT☐ INDUSTRIAL☐ MILITARY☐ MUSEUM☐ PARK☐ PRIVATE RESIDENCE☐ RELIGIOUS☐ SCIENTIFIC☐ TRANSPORTATION☐ OTHER:**4 OWNER OF PROPERTY**

NAME

William F. Huck, et al

Telephone #:

STREET & NUMBER

Saxon Farm

CITY, TOWN

Church Hill

☐ VICINITY OF

STATE, zip code

Maryland 21623

5 LOCATION OF LEGAL DESCRIPTION

COURTHOUSE,

REGISTRY OF DEEDS, ETC.

Queen Anne's County Courthouse

Liber #:

Folio #:

STREET & NUMBER

CITY, TOWN

STATE

6 REPRESENTATION IN EXISTING SURVEYS

TITLE

DATE

☐ FEDERAL ☐ STATE ☐ COUNTY ☐ LOCALDEPOSITORY FOR
SURVEY RECORDS

CITY, TOWN

STATE

7 DESCRIPTION

QA 54

CONDITION		CHECK ONE	CHECK ONE
<input type="checkbox"/> EXCELLENT	<input type="checkbox"/> DETERIORATED	<input type="checkbox"/> UNALTERED	<input checked="" type="checkbox"/> ORIGINAL SITE
<input type="checkbox"/> GOOD	<input type="checkbox"/> RUINS	<input checked="" type="checkbox"/> ALTERED	<input type="checkbox"/> MOVED
<input type="checkbox"/> FAIR	<input type="checkbox"/> UNEXPOSED		DATE _____
	<input checked="" type="checkbox"/> Site		

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The William Huck Farm is located on the north side of Southeast Creek Road immediately to the west of Maryland Route 218 and approximately one-half mile west of Church Hill.

An early house on this farm was noted as recently demolished when the reconnaissance survey of Queen Anne's County was prepared in 1973-74. The only known photograph of the house is a color transparency taken by Michael Bourne.

The house was of frame construction, 1 1/2 stories high, three bays wide and one room deep, with a single flush brick chimney centered on the west end of the gambrel roof. A second exterior chimney of uncertain age is centered on the east gable. The entrance door is off-set to right of center on the south facade, flanked by a single 2/2 window on each side. There are two 6/6 shed roof dormers on the second story. The exterior on the south facade is covered with asbestos shingle siding and a wood shingle roof.

The interior probably consisted of a hall-parlor plan. No details are available regarding the other exterior walls or the interior.

CONTINUE ON SEPARATE SHEET IF NECESSARY

PERIOD	AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW			
PREHISTORIC	<input type="checkbox"/> ARCHEOLOGY-PREHISTORIC	<input type="checkbox"/> COMMUNITY PLANNING	<input type="checkbox"/> LANDSCAPE ARCHITECTURE	<input type="checkbox"/> RELIGION
1400-1499	<input type="checkbox"/> ARCHEOLOGY-HISTORIC	<input type="checkbox"/> CONSERVATION	<input type="checkbox"/> LAW	<input type="checkbox"/> SCIENCE
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> AGRICULTURE	<input type="checkbox"/> ECONOMICS	<input type="checkbox"/> LITERATURE	<input type="checkbox"/> SCULPTURE
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> ARCHITECTURE	<input type="checkbox"/> EDUCATION	<input type="checkbox"/> MILITARY	<input type="checkbox"/> SOCIAL/HUMANITARIAN
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> ART	<input type="checkbox"/> ENGINEERING	<input type="checkbox"/> MUSIC	<input type="checkbox"/> THEATER
<input checked="" type="checkbox"/> 1800-1899	<input type="checkbox"/> COMMERCE	<input type="checkbox"/> EXPLORATION/SETTLEMENT	<input type="checkbox"/> PHILOSOPHY	<input type="checkbox"/> TRANSPORTATION
<input checked="" type="checkbox"/> 1900-	<input type="checkbox"/> COMMUNICATIONS	<input type="checkbox"/> INDUSTRY	<input type="checkbox"/> POLITICS/GOVERNMENT	<input type="checkbox"/> OTHER (SPECIFY)
		<input type="checkbox"/> INVENTION		

SPECIFIC DATES

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

The early house on the William Huck Farm was a 1 1/2 story, 3 bay frame house with a gambrel roof. The interior was evidently divided into a hall-parlor plan. Probably dating to the second quarter of the 19th century, it was demolished in the late 1960's or early 1970's.

CONTINUE ON SEPARATE SHEET IF NECESSARY

9 MAJOR BIBLIOGRAPHICAL REFERENCES

QA-54

CONTINUE ON SEPARATE SHEET IF NECESSARY

10 GEOGRAPHICAL DATA

ACREAGE OF NOMINATED PROPERTY _____

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE

COUNTY

STATE

COUNTY

11 FORM PREPARED BY

NAME / TITLE

Orlando Ridout V, Historic Sites Surveyor

ORGANIZATION

Queen Anne's County Historical Society

DATE

10/14/81

STREET & NUMBER

TELEPHONE

CITY OR TOWN

Centreville


STATE

Maryland

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438



Morgnac

TRAVILLA WHARF

SPRY LDO

Chase I

290

Sutton Pt

BM 18

Champton

BUCKINGHAM WHARF

Possum Pt

Char-hor Manpr

DEEP LDO

DEEP LDO

COHEY RD

DEEP LANDING

RD

RD

RD

RD

RD

RD

RD

RD

RD

RD

RD

RD

RD

RD

RD

RD

RD

RD

RD

RD

RD

RD

RD

RD

RD

RD

RD

RD

RD

RD

RD

RD

RD

RD

RD

RD

RD

RD

RD

RD

RD

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291

291